

ANNEXURE - B.

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 - 1970)

1. Name of the Officer
2. Name of the School
3. Location with name of Education District/ Sub. District
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.

Rifa. P.T
Bench Mark International School Tirun
Annamal, Tirun

R.C.C

GrF - 49.90m x 49.40m

FF - 49.90m x 16.60m

5. Period for which the certificate is issued

2026 - 2027

6. Nature of defects, if any

- a) Foundation and basement
- b) Superstructure
- c) Doors and Windows
- d) Wood work wrought and put up
- e) Roof
- f) Flooring
- g) Miscellaneous (Cracks, etc.)

Nil

7. Any major defects noticed which will render the building unsafe in any manner

Nil

8. Whether maintenance works have been done properly

9. Whether the structure is sound or not for conducting classes

Yes
Sound to conduct classes under Normal
wind and weather conditions.

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

Sheet Roofed Kitchen - Unfit

CERTIFICATE

certified that the school building was inspected by me on 21/05/2026 and
found to be fit / unfit to conduct classes, for the period 2026 - 2027 for the
reasons stated above.

Place : Tirun

Date : 31/05/2026



Rifa PT
PEN: 520291
ASSISTANT ENGINEER
TIRUN MUNICIPALITY